Mond	day, 2/5/2007 8:07:19 AM			
	Inhandra	5		
¥		Process Sheet		
Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: BAR	
Job Number	: 30602		15 8EC	v2
Estimate Number	: 10388	•	OF TOULCE	wh.
P.O. Number	712	Part Number	: D31963	
This Issue	: 2/5/2007 S.O. No. : 14 1/A	Drawing Number	: D3196 UNDER REVIEW	-
Prsht Rev.	, NC	Project Number	: N/A	
First Issue	: NIA Type : MACHINED PARTS		U/R 22.06	
Previous Run	: 28141	Material	: HIA	
Written By	1N n/	Due Date	: 2/9/2007 Qty: 8 Um:	Each
Checked & Approv	red By			ļ
Comment		JLM		
Comment	. ESUNEV. AT INEW ISSUE 00-11-00 0	LIVI		
Additional Product				
		;		
Job Number:				
Seq. #:	Machine Or Operation:	Description :	<u> </u>	
1.0	M6061T6B0750X01500	6061-T6 Bar .75" X 1.5"	144014414	
				·
Comme	ent: Qty.: 3.0345 f(s)/Unit Total: 24.2760) f(s)		
	Material: 6061-T6/T651 (QQ-A-200/8) or (QQ	· ·		· /x ·
	(M6061T6B0.750x01.500)			M,
	Identify for D3196-3			7
	Batch: M 10332	J.F.	07/02/26	(2)
			01102120	
2.0	BAND SAW	BAND SAW	(1888)	
	f [
Comme	ent: BAND SAW			$\widehat{}$
•	Cut blank: (0.75" x 1.50") x 34.750" long Bar	JE	07/02/26	(3)
20:		HAAS CNC VERTICAL MACHINING		
3.0	HAAS1	TAAS ONG VERTIONE MAGINITATO	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		•		
	(I I I I I I I I I I I I I I I I I I I		(
Comme	ent: HAAS CNC VERTICAL MACHINING #1			
	1-Machine D3196-3 as per Folio FA339 and [Dwg D3196Identify as D3196	3-3	
	The second of th	, 1		
	2-Deburr	and ITE.	07/02/26	(S)
		"IODEOT DADTO ACTUEV COME!		
4.0	QC2	INSPECT PARTS AS THEY COME (OFF MACHINE	
Comme	ent: INSPECT PARTS AS THEY COME OFF MA	CHINE THE / T	F. 07/02/26	(8)
5:0		SECOND CHECK	1,70,0	
J.U	FIREFALENTALISMENT FIREFALE	JEOGNE OF IEGI		
				- A
Comme	ent: SECOND CHECK		J.L 07/02/21	(8)
·			7	
	•		~ .	4. 9
				*13

Dart Aerospace Ltd

	WORK ORDER CHANGES							
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
1								
7								
	/	STEP PROCEDURE CHANGE	STEP PROCEDURE CHANGE By	STEP PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr		

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date: <u>07/03/0</u> 5
			QA: N/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A Initial Chief Eng		Initial Action Description Sign &		Verification Section C	Approval Chief Eng	Approval QC Inspector	
0 <i>7</i> /02 26	3	The origine is shift 1040" on the x exes. So the dim., 987" is 1,026 on one side and 1948 on the other	9 67.62.76 PV	Dimension does not affect Stress report. Acceptable	J.F.	07026	67.62.26 pv B1642	Torone	
07/02/26	1	one C'sinkis,040" to wide. Ipiece.	QP 07.02.76 051.042	Dimension does not a fact Shress report . Acceptable	J.F. 07/02/26	107 v 26	67.02.26 per a81042	Parzo	

NOTE: Date & initial all entries

Date: Monday, 2/5/2007 8:07:19 AM User: Kim Johnston **Process Sheet** Drawing Name: BAR Customer: CU-DAR001 Dart Helicopters Services Part Number: D31963 Job Number: 30602 Job Number: Description: Seq. #: Machine Or Operation: HAND FINISHING1 HAND FINISHING RESOURCE #1 6.0 Comment: HAND FINISHING RESOURCE #1 07/02/27 X8 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING 7.0 M101601 Comment: POWDER COATING X8 Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 8.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 10.0 QC21 Comment: FINAL ION/W/O RELEASE N 09.0305 Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				-						
		·								
4										

Part No: _	PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date:
			QA: N	1/C C	losed:	Date:

NCR:	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	** ** **	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector	
				•					

NOTE: Date & initial all entries

DART AEROSPACE LT	D		Work Order:	30602
Description: Bar			Part Number:	D3196-3
Description: Dai		4		
Inspection Dwg: D3196	Rev: BC	\$ 02.02.06		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
34.625	+/-0.010	34.627				
33.650	+/-0.005	33 650				
0.488	+/-0.005	.487"				
17.011	+/-0.010	17,011"				
0.512	+/-0.005	,510"				
1.500	+/-0.010	1,501"	/ /			
0.464	+/-0.010	, 465"				
0.504	+/-0.010	506"	V ,			
Ø0.344	+0.006/-0.001	Ø,348°				
Ø0.660 x 100°	+0.008/-0.001 x 0.5°	B.660"				
0.962	+/-0.005	.961"				
0.750	+/-0.010	747"				· ·
4.750	+/-0.010	4,750"			,	
12.531)	+/-0.010	12,531"				
16.999	+/-0.010	16,999"				
21.844	+/-0.010	21,844"				
29.625	+/-0.010	29,625				1911
0.250	+/-0.010	,250"	//			·
1.000	+/-0.010	1,000"				
R0.125	+/-0.010	RO. 125"				·
0.987	+/-0.010	,986				
0.060 x 45°	+/-0.010 x 0.5°	055 445				


Measured by: T.F.	Audited by:	az	Prototype Approval:	N/A
Date: 07/02/26	Date:	04.02.26	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.04.20	New Issue	KJ/RF	
В	06:10.24	Dwg Rev. updated	KJ/JLM	8
			. ()	



RELEASED





CHAMFER 0.060x45*

ENGRAVE P/N IN AREA SHOWN USING 0.15 HIGH x 0.005 DEEP

(TYP 10 PLACES)

LETTERING

DOCUMENT

ᅜ

Copyright © 2003 by DART AEROSPACE PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM

NOT TO BE USED F

E P

ANY PURPOSE

욹

COPIED

R_{0.125}